STATES OF T

DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

SUBJECT: REPAIR STATION LIMITED RATINGS BEECH 18 SERIES AIRCRAFT

- 1. <u>PURPOSE</u>. The purpose of this advisory circular is to advise of a required limited repair station rating to perform X-ray inspection of the Beech 18 Aircraft Wing and Center Section Spar, and the procedures for application. It also provides information concerning certification procedures and operating requirements.
- 2. REFERENCES. FAR 145, 65, and Airworthiness Directive (AD) 75-27-09
- 3. <u>BACKGROUND</u>. Findings of compliance with previous X-ray inspection ADs, (AD-72-20-5, 73-18-4, and 75-09-18), have shown substandard performance. In many instances X-ray plates were made, interpreted, and given to the owner or operator with the assurance that the aircraft was airworthy. However, when the plates were evaluated by FAA engineering personnel, or by Beech Aircraft Corporation, the plates showed that cracks existed, or were suspected, or the quality of the plates was such that a satisfactory interpretation could not be made.
- 4. NEW AIRWORTHINESS DIRECTIVE. A new AD, 75-27-09, has been published to correct the situation described above. It cancels the previous ADs on this subject and combines all the provisions in one AD. In view of past experience and due to the unique and special inspection procedures described in the directive, it has been determined that only fully qualified facilities and personnel can adequately accomplish the inspections. Accordingly, after July 1,1976, the only maintenance entity that will be authorized to accomplish the X-ray inspections will be an FAA certificated repair station rated as, "Limited Airframe - Beech 18 Series Aircraft - Wing and Center Section Spar X-ray Inspections." It should be pointed out, however, that the X-ray inspection is only one part of the total compliance with the AD. In addition, a visual inspection and either a magnetic particle or penetrant inspection are required. The latter two can be performed and approved for return to service by a properly qualified airframe mechanic or an appropriately rated repair station.

Initiated by: AFS-830

(See Appendix 1). The applicant completes items 1 through 5. The following information should prove helpful in selecting the proper method of listing the repair station:

Item 1A: Official Name of Station

An Individual
Joe J. Doe d/b/a
Daro Aviation Service

A Corporation

Daro Aviation Service, Inc.
or

Daro Aviation Inc. d/b/a

Daro Aviation Services

A Partnership
John J. Doe, Allen B. Smith
Richard Roe d/b/a
Daro Aviation Service

Item 3: Rating Applied For

See Appendix 1

Item 4: List of Maintenance Functions Contracted to Outside Agencies

Since this is a limited rating to perform a unique and special inspection, special equipment and materials to perform the work are necessary. The word "none" should be entered in item 4.

7. PERSONNEL AND AIR AGENCY QUALIFICATIONS. FAR Section 145.39 requires that a repair station provide adequate personnel who can perform, supervise, and inspect the work for which the station is rated. Therefore, only those agencies and persons who have demonstrated the capability to reliably perform the inspections set forth in AD 75-27-09 can be authorized to perform these inspections. The applicant is expected to show the ability to satisfactorily perform the required X-ray procedures. This may be accomplished by presentation of acceptable X-ray films taken per AD 75-27-09 or an AD superseded by AD 75-27-09. To determine the capabilities of personnel, the FAA will provide a set of test X-rays plates for the person to read and interpret using the applicant's viewers and facilities. This person may be a certificated mechanic holding an

Page 2

Par 5

- there are so many variables, and past experiences have shown a problem in this area. The applicant for this rating should prepare an inspection procedures manual that contains instructions and procedures for inspection personnel to be thoroughly familiar with all X-ray inspection methods, techniques, and equipment. They should also have available, understand, and comply with the current specifications contained in the operations specification of the station.
- 9. <u>INSPECTION FOR CERTIFICATION</u>. An applicant should contact the FAA District Office, giving as much lead time as possible to allow for scheduling of inspections. This should be accomplished when the applicant believes that the applicable requirements of FAR 145 have been satisfied.
 - a. The applicant should present with the application, or as soon as possible thereafter, a set of X-ray films taken by him in accordance with AD 75-27-09 or an AD superseded by AD 75-27-09. If previous X-ray films taken by this facility are not available locally but are on file with the Beech Aircraft Corporation, the applicant should present sufficient data so that FAA can obtain these films for evaluation.
 - b. The FAA will notify the applicant of the results of the evaluation and, if appropriate, schedule a date for examination of the qualification of the personnel who will be authorized to review and interpret the films. Any changes in authorized personnel, facilities, repair station equipment, or the inspection procedures established at the time of certification will require FAA evaluation and approval prior to the repair station exercising the privileges of their certificate.
- 10. REPAIR STATION CERTIFICATE AND OPERATIONS SPECIFICATION. Upon meeting all requirements the FAA District Office will issue an Air Agency Certificate (See Appendix 2) and Repair Station Operations Specification. (See Appendix 3). The operations specifications, in addition to describing the limitations applied to the station, indicate the specification to be used by the station in performing the X-ray inspections. The airworthiness directive is the primary part of the specification. The other part of the specification may be either a civil or military specification currently used by the industry and approved by the Administrator. The

accordance with FAR 145.59.(a). The person performing the X-ray inspection is also required by this AD to enter the date of letter of authorization issued by the FAA District Office in the maintenance records specifically in FAR 91.173 (a)(2).

12. OTHER RATINGS. Nothing in this advisory circular (AC) should be construed as preventing a repair station with this rating from having other ratings. This rating can also be added to an existing repair station certificate when all requirements have been met.

J. A. FERRARESE, Acting Director

Flight Standards Service

J. a. Ferrarese

Page 4

Bay View Airport					OTHER (Specify)						
B	ay View, Ohio	L1463									
c. o	FFICIAL MAILING ADDRE	SS OF REPA	IR STATION (Num	ber, street,							
F	2.0. Box 1A										
Ė	Bay View, Ohio	11463		ļ							
3. RATINGS APPLIED FOR CLASS				LIMITED		4. LIST OF MAINTENANCE FUNCTIONS CONTRAC					
X	AIRFRAME		Limited Ai	rframe-Bee	ch	TO OUT	IDE AGENO	CIES			
	POWERPLANT		1				NONE				
				And Center Section		<u>on</u>					
	RADIO	Spar X-ray	X-ray Inspections								
	INSTRUMENT										
	ACCESSORY										
	SPECIALIZED SERVICE										
				ICANT'CERTI							
N A M	E OF OWNER (Include t	name(s) of i	ndividual owner,	all parmer, or	corp	oration nan	ne giving s	tate and date of incorporation)			
	F. Jones			-							
	reby certify that I have t attachment hereto are tr				ied in	item 1 to	make this a	application and that statements			
DAT	E TIT	LE					ED SIGNAT				
М	ay 30, 1976	Genera	1 Manager	_		A.F.	Jones	a. F. Jonese			
			<u> </u>					,			
Ī	FOR FAA USE ONLY			RECORD OF ACTION PAIR STATION INSPECTION				Keports Identification Symbol FS 8320-5			
						·					
6. REMARKS (Identify by item number. Include deficiencies found, ratings denied)											
				- RECOMMENDA		<u> </u>					
X	A. STATION WAS FOUND						DEFICIEN	CIEC LICTED IN ITEM 6			
37								CIES LISTED IN ITEM 6. 8. DATE OF INSPECTION			
X	C. RECOMMEND CERTIF							6. DATE OF INSPECTION			
	D. RECOMMEND CERTIF	RATING APPLIE	S APPLIED FOR ON APPLICATION (Except those			June 15, 1976					
9.	OFFICE	OFFICE			SIGN	TOR (S)					
					_	1					
AS	W-GADO-9	A. C	Carry	<u>.u.</u>	Car	ry					
ASW-EMDO-10				B. Long B. Long							
العط	H-BHDO-TO										
10. SUPERVISING OR ASSIGNED INSPECTOR											
ACTION TAKEN CERTIFICATE ISSUED INSPECTOR'S SIGNATURE											
	1	NUMBER			m			•			
х	APPROVED AS SHOWN ON CERTIFICATE ISSUE	D 007	. 00	H. Smi	•						
	ON DATE SHOWN	DATE	-00			neral	Aviation	n District Office			
	DISAPPROVED	.Tu 1	y 2, 1976	ASW-G							
	<u> </u>	1 001	,								

FAA Form 8310-3 (1-68) SUPERSEDES FAA FORM 394 AND FAA FORM 3572

C FAA AC 69-2897

GPO 937-20

	,			•
		-		
				•

Number 007-00

This certificate is issued to

A.F. Jones d/b/a
Bay View X-ray
whose business address is

Bay View Airport
Bay View, Ohio 11463

upon finding that its organization complies in all respects with the requirement of Allefal Aviation Regulations relating to the establishment of an Air Agency, and is empowered to operate an approved

with the following ratings:

LIMITED AIRFRAME - BEECH 18 SERIES AIRCRAFT - WING AND CENTER SECTION SPAR X-RAY INSPECTIONS

This certificate, unless canceled, suspended, or revoked; shall continue in effect INDEFINITELY

By direction of the Administrator

Date issued:

7/ Lith

July 2, 1976

H. Smith

Chief, General Aviation District Office, This Certificate is not Transferable, and any major change in the basic facilities, or in the location thereof, ASW-GADO-9 SHALL BE IMMEDIATELY REPORTED TO THE APPROPRIATE REGIONAL OFFICE OF THE FEDERAL AVIATION ADMINISTRATION

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both

FAA Form 8000-4 (1-67) SUPERSEDES FAA FORM 390.

Page 1

		-		

Limitations:

The rating (*) set forth on Sir Agency Cortificate Number 007-00 is are limited to the following: Beech 18 Series Aircraft—Wing And Center Section Spar X-ray Inspections.

The specification to be used for this function is Airworthiness Directive 75-27-09 or an AD superseding AD 75-27-09 and MIL-STD-00453A. The Airworthiness Directive will take precedence in any conflicting detail between it and any other specification used.

This rating is issued based on the satisfactory FAA evaluation of the repair station's radiographs and their personnel's interpretation of FAA test films. X-ray inspection conducted under this rating must be of the same quality as those presented to obtain this rating. Any changes in facilities, authorized personnel, repair station equipment, or the inspection procedures established at the time of certification, will require FAA evaluation and approval prior to the repair station exercising the privileges of their certificate.

SAMPLE

Delegated authorities: None

Date issued or verised:

July 2, 1976

FAA Form 890.1 Page 9 (11-63) USE PREVIOUS EDITION

For the Administrator:

H. Smith

H. Smith
Chief, General Aviation District Office

ĄŞW<u>. C</u>ĄDO-9

Page 1

	·	
	-	